

# HARPON 325

Frequent contact | continous wear



Comfort and safety when gripping heavy, rough or slippery objects in highly aggressive environments

## SPECIFIC ADVANTAGES

### 差 Cut protection

• A long cuff for a better protection of the forearm

### Thermal protection

• Suitable for long-term wear, due to the comfort of a textile support and good thermal insulation

### Durability

• Optimised service life: high resistance to abrasion

### (Q) Guaranteed quality

• Silicone free to prevent traces, defects on metal sheet and glass prior to painting



- Food industry
- Fishing

## APPLICATIONS

- Fish-handling
- Oyster farming
- Work with frozen products
- Fishing

#### Edit 05/05/2021

MAPA SAS capital de 35.000.010 € 420, rue d'Estienne d'Orves 92705 Colombes Cedex France RCS Nanterre 314 307 720






# HARPON 325

Frequent contact | continous wear

## LEGENDS





K: Sodium hydroxide 40% P: Hydrogen peroxide 30% T: Formaldehyde 37%

## PRODUCT DETAILS

Interior finish	Textile support
Exterior finish	Reinforced grip
Material	Natural latex
Cuff characteristic	Feston Cuff
Colors of the gloves	Orange
Length (cm)	37
Thickness (mm)	1.35
Size	8 9 10

## LOGISTIC DETAILS

Packaging	1 pair/bag 5 pairs/box 50 pairs/carton	
-----------	--	--

## LEGISLATION

- This product is not classified hazardous according to the regulation (EC)  $n^{0}1272/2008$  of the European Parliament and of the Council.
- This product does not contain more than 0.1 % of substance of very high concern (SVHC) or any substance included in the annex XVII of the regulation n° 1907/2006 of the European Parliament and of the Council (REACH).
- UE type certificate or CE type examination certificate: 0075/014/162/01/19/0245 ext 01/01/19
- Issued by the notified body nr: 0075 CTC 4, rue Hermann Frenkel 69367 Lyon Cedex 07- FRANCE
- Quality assurance certificat: 0334 Asqual 14 rue des Reculettes -75013 Paris -France

Edit 05/05/2021

MAPA SAS capital de 35.000.010 € 420, rue d'Estienne d'Orves 92705 Colombes Cedex France RCS Nanterre 314 307 720

